# Product Change Notice

## EPI-LX800 Version Change

- **Notification #: 2010010002**

- **Date of Publication: Jan 18$^{th}$, 2010**

- **Affected Model: EPI-LX800**

- **Change Description**

  The change is mainly to solve the issue that RTC timing reset are found on EPI-LX800 Rev.A1 occasionally.

  In order to provide a better quality and stability, I2C RTC circuit (Circuit 1) is added to settle this issue.

  **Circuit 1**



- **Customer Impact of Change and Recommended Action**

  Customers need to update their ordering process to place next orders with new P/N: EPI-LX800-A2R.

● **Product Affected / Avalue P/N**

| Model Name | P/N |
|------------|-----|
| EPI-LX800 | EPI-LX800-A2R |

We apologize for any inconvenience this may cause and appreciate your understanding.

Thank you for your confidence in us in the past and look forward to serving you better in the future.

Sincerely yours,

Sam Wang
Technical VP